

Figures




Figure 1. Vickers hardness (HV) versus TMA exposure time at 120°C infiltration temperature




Figure 2. Photograph of PMMA pieces in order of increasing TMA exposure time upon infiltration at 120°C