

Fig 1: Composition profiles, depicting the change in composition of the coating across its depth, obtained from EDS maps. The hafnium, aluminum and boron content within the coating is uniform, and does not change after any heat treatment. For the oxide, the aluminum content in the oxide increases due to the hold at $700^{\circ}C$