

Figure 1. Schematic of thermal Ni and Co ALE surface chemistry based on sequential exposures to SO₂Cl₂ and PMe₃.




Figure 2. QCM mass change over a) two cycles of nickel ALE and b) two cycles Co ALE using SO₂Cl₂ and PMe₃ at 150 °C.