

Fig 1) Left: Optical microscope image of the analysed junction. Moving to the right of the figure: The reconstructed intensity image of the HEXRR-tomo obtained by combining different HEXRR images and different positions on the sample. Lower angles reveal the morphological imperfections at the junction borders.