Step	3-D view	Top view	Cross-sectional view	Note
A			4	Master
В	000			Soft stamp
С				Imprint on silicon
D		•••		Descumming and masking
Е		000		Etching
F	\$			Oxidation
G		88		Soft stamp
Н				Imprint on glass
Ι		88		Etching

Table 1: Schematic illustration of the fabrication processes.